

NOTE

1. CHAMFER TOPS AS SHOWN
2. HEADER SHALL BE STRAIGHT WITHOUT KINKS OR BENDS OR GRAVEL BETWEEN BOARDS
3. PROTECT REDWOOD HEADER AT ALL TIMES. REPLACE DAMAGED HEADER AND ASPHALT. REPAIR AT CONTRACTOR COSTS.
4. LAYOUT PLAN AND DETAILS TO DETERMINE DEPTHS OF MATERIALS.

\\Cpd-planning\cpd_planning\2 Campus Standards\STANDARD SPECS\3 SITE FURNISHINGS CAD DETAILS\CAD Furnishings Details\Current Details




WOOD HEADER

Scale: NTS

Stanford University Architect/Planning Office
Standard Campus Site Furnishings Guidelines

Updated: 08/28/07

Superseded: 11/28/07



\\Cpd-planning\cpd_planning\2 Campus Standards\STANDARD SPECS\3 SITE FURNISHINGS CAD DETAILS\CAD Furnishings Details\Current Details



STEEL HEADER AT STONE FINES

Scale: NTS

Stanford University Architect/Planning Office
Standard Campus Site Furnishings Guidelines

Updated: 02/15/08

Superseded: 12/20/07